



بِسْمِ اللَّهِ الرَّحْمَنِ الرَّحِيمِ

**MINISTRY OF TRANSPORT AND COMMUNICATIONS  
CIVIL AVIATION DEPARTMENT**

Male'  
Republic of Maldives

---

## **AIRWORTHINESS DIRECTIVE**

No. CAD/C-208/3  
26 September 1994

---

### **APPLICABILITY**

Cessna Caravan  
Model : 208  
Serial Nos: 20800155 upto 20800238

### **SUBJECT**

Flap Bellcrank Bolt Inspection/Replacement

### **REFERENCE**

Service Bulletin CAB94-14 dated July 19, 1994

### **REASONS**

There have been reports of the forward right primary flap bellcrank attach bolt failing in the threaded area. To assist in preventing this condition from occurring, an inspection of the bellcrank installation and replacement of the effected bolt shall be accomplished.

### **ACTION AND COMPLIANCE**

Action to accomplish work in accordance with the Service bulletin CAB94-14, dated 19 July 1994 within the next 100 flying hours or 12 months, whichever occurs first. Non-compliance with the Service bulletin may result in failure of the bellcrank attach bolt, an asymmetric flap condition and damage the secondary wing structure.

### **EFFECTIVITY**

This Directive becomes effective on 26 September 1994.

Abdul Razzak Idris  
**DIRECTOR OF CIVIL AVIATION**