



بِسْمِ اللَّهِ الرَّحْمَنِ الرَّحِيمِ

**MINISTRY OF TRANSPORT AND COMMUNICATIONS
CIVIL AVIATION DEPARTMENT**

Male'
Republic of Maldives

AIRWORTHINESS DIRECTIVE

No. CAD/C-208/4
06 November 1994

APPLICABILITY

Cessna Caravan
Model : 208
Serial Nos: 20800001 upto 20800237

SUBJECT

Right hand Airspeed Indicator Inspection

REFERENCE

Service Bulletin CAB94-15 dated October 14, 1994

REASONS

It has been determined that some right hand panel mounted airspeed indicators may have had the upper end of the white arc extending to 130 Knots instead of the required 125 Knots. Since some of these airspeed indicators may have been installed in new airplanes or sold through Cessna Parts Distribution as spares, an inspection of the indicators for this condition is required.

ACTION AND COMPLIANCE

Action to accomplish work in accordance with the Service bulletin CAB94-15, dated 14 October 1994 within the next 100 flying hours or 12 months, whichever occurs first.

EFFECTIVITY

This Directive becomes effective on 06 November 1994.

Abdul Razzak Idris
DIRECTOR OF CIVIL AVIATION