



بِسْمِ اللَّهِ الرَّحْمَنِ الرَّحِيمِ

DEPARTMENT OF CIVIL AVIATION

Male'

Republic of Maldives

AIRWORTHINESS DIRECTIVE

No. DCA/DO-228/18

21 June 1993

APPLICABILITY

Dornier 228-200/201/202/212
Serial Nos: All Serial Numbers

SUBJECT

Inspections for cracks in Horizontal Stabilizer Rib

REFERENCE

Dornier SB-228-211, dated April 23, 1993

REASONS

During Dornier Structure Inspection Programme, some cracks were found at Horizontal Stabilizer Ribs.

ACTION AND COMPLIANCE

Action to accomplish work in accordance with Dornier SB No: 228-212 dated 23 April 1993 within 3 months from the date of effectivity of this Directive.

EFFECTIVITY

This Directive becomes effective on 21 June 1993

Mohamed Shareef
DIRECTOR OF CIVIL AVIATION